KARMIK OUTDOORS SIZE & FIT GUIDE



- 1. Cut Out Decal
- 2. Place On Gear
- **3. Test Location**
- 4. Buy Our Decals Today!

Buy Now

Permanent Decal Application

Clean application surface, preferably with 70% isopropyl alcohol •Application surface must be completely dry after cleaning •Apply decal using firm and even pressure for at least 30 seconds •For best results, decals and application surface should be at a minimum temperature of 70° F (21°C) •Allow decal adhesive to cure for a minimum of 24 hours prior to exposure to water